

Published date	06/21/2016
Document number	SUPAIR_2016/06_002
Page number	1 / 4

## SAFETY WARNING

**SUBJECT :** Chest strap's Safe-T buckle inadvertently opening in flight

**PRIORITY STATUS**

- LOW
- MEDIUM
- CRITICAL

### Problem description :

Inadvertent openings of the aluminum self-locking chest strap buckles were noticed in flight on a few SUP'AIR harness models.



### Concerned products :


SUP'AIR harnesses equipped with self-locking aluminum buckles :

- ALTIRANDO 2 RS
- DELIGHT 2
- PIXAIR
- PARAMOTEUR EVO
- SKYPPER
- VIP 2
- VIP LITE

- There is the possibility for other harness models to have been equipped with faulty self-locking buckles.

### Facts/ Ascertainment :


A few aluminum self-locking chest strap buckles used on selected SUP'AIR harness models may have experienced inadvertent opening in flight. The buckles sudden releases only concerns the "Safe-T" strap and rarely happens. The problem comes from a manufacturing defect invisible by the naked eye and non reproductive during a test.



Next page ►

## Procedure to follow :

*How to identify if my harness is concerned ?*



If your harness corresponds to the above references :

- 1) Stop flying with this harness
- 2) Contact your nearest dealer/distributor or SUP'AIR directly
- 3) Depending on your harness model, an upgrade procedure will be made available to you.

Next page ►

<b>Published date</b>	06/21/2016
<b>Document number</b>	SUPAIR_2016/06_002
<b>Page number</b>	3 / 4

Where to find the self-locking buckles stamp information ?



Example :

06 / 15

RQ : If the stamped information is not visible, please contact us !

Steps to follow in case of a suspected problem :

- **Stop flying with the problem harness.**
- Fill out the form " Self-locking chest strap buckle - swapping/upgrade procedure" ( see below ).
- Contact your dealer or distributor who will help you with the steps to follow :

Your harness can be repaired at home: a new "Safe-T kit" will be sent to you in order to conduct the operation yourself and safely fly afterward.

Concerned harness models :

- ALTIRANDO 2 RS
- PIXAIR
- PARAMOTEUR EVO
- SKYPPER

See the "T" swapping instruction notice

- DELIGHT 2

See the "T" swapping instruction notice for DELIGHT 2

- VIP 2
- VIP LITE

See the "T" swapping instruction notice for VIP 2

You also can contact SUP'AIR directly at the following address: [sav@supair.com](mailto:sav@supair.com)  
We will reply as soon as possible.

The SUP'AIR Team

Next page ►

Published date	06/21/2016
Document number	SUPAIR_2016/06_002
Page number	4 / 4

Form to fill out :

**Chest strap self-locking buckle - upgrade procedure**

Harness model : .....

Self-locking information stamping : ..... and .....

Harness owner's name : .....

Postal address : .....

Phone number : .....

E-mail address : .....

Person able to perform the harness :

- USER                       DEALER                       MANUFACTURER

Person able to conduct the repairs :

- USER                       DEALER                       MANUFACTURER

*Except if professional repair is necessary.*

**DELAIS : The inspection must be done immediately**

Documents recipients :

- USERS                       DEALERS                       SCHOOLS
- CLUBS                       MAGAZINES                       ASSOCIATIONS

Safety Warning : SUPAIR\_2016/06\_002

