Published date12/12/2018Document numberSUPAIR_2018/12/002Page number1 / 2

Facts/ Ascertainment :

The upper lateral backrest tilt adjustment strap might start to tear during use. This tear can lead to a complete rupture of the strap. This specific strap does not affect the harness' structure but might impact the support of the pilot, making the harness uncomfortable especially if the second adjustment strap is not set properly.

This can also lead to a lack of position awareness and support of the pilot and might have consequences on certain phases of flight.

Suite page 2 ►

SUPAIC





Problem description :

may be damaged in the adjustment buckle.

SUBJECT : ACRO BASE harness

Lateral adjustment straps tear


Caution, the side backrest adjustment strap (higher one)







S U P A I C




ACRO BASE harness Indice A1 à B4



| Published date | 12/12/2018 |
|-----------------|--------------------|
| Document number | SUPAIR_2018/12/002 |
| Page number | 2/2 |

Procedure to follow:





Communiqué sécurité : SUPAIR_2018/12_002

 SUPAIR - 34, rue Adrastée - 74 650 CHAVANOD - FRANCE

 Tel : +33 (0)450 457 529 - e-mail : info@supair.com